



Network Homes

Safety in your building

22 July 2022

11 and 17 Robsart Street, 1 and 7 Thornton Street,
Stockwell,
SW9

The Hive
22 Wembley Park Boulevard
Wembley
HA9 0HP

www.networkhomes.org.uk
customerservice@
networkhomes.org.uk
0300 373 3000

Dear residents,

Lender letter available which may help you to sell or remortgage

I'm pleased to say that we are now able to provide you with a 'lender letter' which may mean you are able to sell or remortgage your property. I know there have been several residents who have been waiting patiently to be able to do this, so I'm extremely pleased to be able to provide you with this letter and I'd like to thank you again for your understanding.

View the lender letter on the dedicated webpage for Cumnor House, Helmi House and Lidcote House:
www.networkhomes.org.uk/robsart2buildingsafety/

What is the new EWS1 form guidance?

We told residents at the recent webinar that there is new guidance on EWS1 forms. Some lenders have stated that they will be willing to lend on a property without an EWS1 form, if they are provided with an outline of the work required, the start and finish dates, and a fully funded plan.

This means that for those of you looking to sell or remortgage, you can get started on that process now and you won't have to wait until the project is completed and you receive an EWS1 form. Of course, this is not a guarantee that a lender will lend on your specific property, however we have seen properties sell already at other buildings where we did not yet have an EWS1 form.

Which lenders does this apply to?

As of March 31, the following lenders had agreed to the new EWS1 form guidance:

- Barclays Bank
- HSBC
- Lloyds Banking Group
- Nationwide Building Society
- NatWest
- Santander.

You can read more about the announcement here: <https://www.ukfinance.org.uk/policy-and-guidance/guidance/joint-statement-cladding>.

Where can I find the letter?

We've included a copy of the letter below this update explaining the guidance so you can have a read of it. We've also uploaded it to the dedicated webpage (in the purple box above) listing all your building's documents, so that you have it as a single page pdf ready to send to lenders.

We'd be grateful if you could let us know how your sale/remortgage is progressing so that we can always have the most accurate picture of how the guidance is working in the sector. If you have any further questions, please get in touch with us on customerservice@networkhomes.org.uk.

Best wishes

Raj Gandecha
Head of Resident Management (Building Safety)

22 July 2022

The Hive
22 Wembley Park Boulevard
Wembley
HA9 0HP

To whom it may concern,

www.networkhomes.org.uk
customerservice@
networkhomes.org.uk
0300 373 3000

9, 11, 13, 15, 17 and 19 Robsart Street and 1, 3, 5, 7, 9 and 11 Thornton Street, Stockwell, SW9 – external wall remediation

Please find the below information relating to the required remediation work to the external wall system at the following addresses, for the attention of lenders:

- 9 Robsart Street, SW9 OAE
- Flats 1-28 at 11 Robsart Street, SW9 OAE
- 13 and 15 Robsart Street, SW9 OAE
- Flats 1-6 at 17 Robsart Street, SW9 OAE
- 19 Robsart Street, SW9 OAE
- Flats 1-6 at 1 Thornton Street, SW9 OBL
- 3 and 5 Thornton Street, SW9 OBL
- Flats 1-9 at 7 Thornton Street, SW9 OBL
- 9 and 11 Thornton Street, SW9 OBL.

These are the typical questions asked by lenders when looking at whether to lend on a property which may be affected by external wall issues.

1. Has there been a review of the building, commenting on external wall in relation to fire safety being carried out in accordance with the latest government advice?

Yes, a review has been carried out by a qualified fire engineer, which has identified issues within the external wall system.

2. Did the review result in any remedial works being required to the building?

Yes, work is required to replace cladding panels, as well as the insulation and cavity barriers behind them. In addition, cavity barriers need to be installed behind brickwork and the EPS render system needs to be replaced.

3. Have the works been completed/commenced?

Work is due to begin on Monday 25 July and is expected to complete by May 2023.

4. Will any costs be passed on to the leaseholders?

Leaseholders will not have to contribute to the remediation of the above issues in the external wall system.

5. What is the current rating stipulated on the EWS1 form for this block?

Once the work is completed, the EWS1 form rating will be B1.

6. Who will be issuing the revised EWS1 form when the external works are completed?

The EWS1 form will be issued by fire engineering firm IFC. Further information on IFC can be found on their website: <https://www.ifcgroup.com/>. The form will be posted on the FIA Portal once it is available: <https://www.fia.uk.com/>.

Kind regards

Suraj Shah
Head of Building Safety